

Photos of building to be demolished









Conclusion

As you can see from the attached photos all the roof is sealed and was replaced approximately 8 years ago and the internals have been fitted out to create workshop and small storage room.

So no ecology report will be required for this planning application.