

Existing Front Doors

- The current doors need replacing as they are in poor condition and have extremely poor thermal properties
- Following advice from the heritage officer the current yellow door of number 36 does not conform to the heritage feature of the building, being a Georgian-style door with fanlight.
- The current black door of number 38 is a ledged and braced door design and thus in keeping with the heritage features. However, it is in poor condition and has extremely poor thermal properties.



Proposed Front Doors

- We propose replacing both doors with a ledged and braced design in keeping with the heritage features
- Both doors will be constructed of good quality English timber and be painted black
- P003.10-501_Proposed_Replacement_Timber_Front_Door

