


Existing Canopy

- The existing canopy detail has failed
- The timber substrate is in poor condition and the weathering details are **derogated** beyond use
- Existing brackets are in poor condition



Proposed Canopy

- We propose replacing the structure like-for-like
- This will consist of new timber substrate, new L brackets (in keeping with the heritage features), and new lead covering and flashings
- It will be made with a 3 degree fall.
- P003.10-502_Proposed_Replacement_Entrance_Canopy-Rev-01



CANOPY SECTION A - A
Scale 1:5

