



1st floor north bay

Bay detaching from front wall



1st floor north bay

Bay detaching from front wall



Ground floor north bay

Window head supported on acroprops



Ground floor north bay

Failed timber and render window surround



Ground floor snorth bay

Failed timber corner detail and cill

STANLAKE PARK MANOR HOUSE

PHOTOSHEETS

NTS

Janaury 2025

2401-EX-8

CRANE&ASSOCIATES

1 Dawes Court Esher Surrey KT10 9QD
01372 470524
www.craneassociates.com