



1st floor north bay
Bay detaching from front wall



1st floor north bay
Close up showing foam pipe insulation stuffed into gap between window and wall



1st floor north bay
Central mullion and casement windows
Casements do not close and frame is no longer weatherproof



1st floor north bay
Central mullion and casement windows
Casements do not close and frame is no longer weatherproof



1st floor north bay
Mullion and casement windows
Casements do not close and frame is no longer weatherproof



1st floor north bay
Close up showing fixed light fixing and poor cement based repair to external stonework which intself has now failed



1st floor north bay
South east mullion showing poor quality cement based stonework repair



1st floor north bay
stonework in very poor conditon, with extensive cement based repairs (now in very poor condition) and inappropriate paint finish

STANLAKE PARK MANOR HOUSE
PHOTOSHEETS

NTS
Janaury 2025

2401-EX-11

CRANE&ASSOCIATES

1 Dawes Court Esher Surrey KT10 9QD
01372 470524
www.craneassociates.com