



2nd floor

Render in poor condition internally and externally. External render spalling

Window cannot be closed due to structural movement and construction detail of window binding on internal render



STANLAKE PARK MANOR HOUSE

PHOTOSHEETS

NTS

January 2025

2401-EX-12

CRANE&ASSOCIATES

1 Dawes Court Esher Surrey KT10 9QD
01372 470524
www.craneassociates.com