




A) Front elevation of store building showing roof deflection over garage doors and affect on main roof ridge and structure



B) Rear elevation of store building showing distortion of main roof ridge

C) Close up view of showing deformation of roof eaves over garage doors with timber post outlined in red





D) Junction of top of post and beam showing deflection and splitting



E) Rotten base of existing timber post

F) Acro prop to support existing lateral beam



G) Roof deformation at eaves over garage doors

