



ASHRIDGE FARM BARNs

Photographic record – Unit 5


Introduction

This photographic record document should be read in conjunction with Green Oak Carpentry's repairs schedule and specification as the analytical record for the timber framed barn.


In order to record the historic fabric and existing features of the barns at Ashridge Farm a photographic record has been undertaken as a means of best conservation practice. A series of internal and external photos have been taken of each of the five properties with a brief description of any key features or craftsmanship. Particular attention has been paid to Unit 5 being the timber frames barn due to that being the Grade 2 listed building. The numbers shown of the elevation plans correspond with the photo numbers for the location the photo was taken. Directional arrows of the photo angle have also been included.

Unit 5


External façade – southern elevation, facing courtyard.




Northern elevation, facing public highway.




Gable ends – Western elevation



Eastern elevation



Eastern elevation of porch



Existing floor plan – Ground floor

Photo 1 – Southern elevation



Photo 2 – South-eastern corner panels in timber frame



Photo 3 – South-east corner elevation



Photo 4 – Northern elevation and porch



Photo 5 – East and Northern elevations



Photo 6 – Window to North elevation Bay 4



Photo 7 – Bay 7, hayloft ground floor



Photo 8 – Roof Bay 7, hayloft first floor



Photo 9 – Roof Bay 7 wattle and daub panels



Photo 10 – Roof Bay 7 wattle and daub panels



Photo 11 – Bay 6 facing East



Photo 12 – Bay 5 Northern wall panel



Photo 13 – Roof Bays 4 and 5 facing North



Photo 14 – Bay 2 North wall panel



Photo 15 – Porch facing North from main barn



Photo 16 – Porch roof bay facing North



Photo 17 – Bay 3 - Main southern barn doors



Photo 18 – Bay 3 Roof section facing south



Photo 19 – Bay 1 – Window in brickwork to west elevation



Photo 20 – Internal bays 2-6 facing East from Bay 1




Photo 21 – Bay 2 wall section facing northeast



Photo 22 – Bay 4 facing southeast detail of wall section showing additional wall cladding



