



Photograph 1: Site entrance from Lodge Rd



Photograph 2: Possible main river looking south



Photograph 3: Structure over waterway



Photograph 4: Culvert in northern direction



Photograph 5: Ponding at eastern side of site



Photograph 6: Northern site boundary depression



Photograph 7: Wet area in eastern area of site



Photograph 8: Ponding at northeastern boundary



Photograph 9: Slight ponding at northwestern site edge



Photograph 10: Manhole in a northeastern direction from site



Photograph 11: Depression at northern boundary



Photograph 12: Ditch along western site boundary



Photograph 13: Corner of Hogmoor and Poplar Lane



Photograph 14: Ditch at site of Poplar Lane



Photograph 15: Main river northeast of site



Photograph 16: Poplar Lane