




Vehicle tracking - articulated lorry entering site