




Vehicle tracking - articulated lorry leaving site