



Reso/Win/Spandrel/SK03 page 1 of 2

Images showing typical sprayed glass failure



