



Method Statement

Method Statement

Task Description	Sign Installation/Cable Installation	Location	Sultan Indian Restaurant 7 Marker Place Wokingham RG401AL	Date	01/11/24
------------------	--------------------------------------	----------	--	------	----------



Methods Used

- 1) We will be installing the sign , With alluminium sign angles made up of 3mm thickness . The material will be galvanised Alluminium Metal Shown in Illustration, these will be drilled in the fascia board using wood screws.
- 2) Second method for the installation of the cabling to illuminate the sign will to pre drill a 50mm Hole (as shown in the illustration red dot). We will feed 12v Time Black/Red 24 Strand Cable Coil). This will be connected to the power supply which will be housed indoors in a suitable location requested from client .



Method Statement

Task Description	Sign Installation/Cable Installation	Location	Sultan Indian Restaurant 7 Marker Place Wokingham RG401AL	Date	01/11/24
------------------	--------------------------------------	----------	--	------	----------

Hazard / Consequences	Control Procedures	Likelihood (a)	Severity (b)	Risk Ranking (= a x b)
Falls from height leading to death, major injury	All staff required to work at height are competent, experienced and have received training. Scaffold and access to height will be erected by competent contractors; staff will follow site safety rules for access and working from scaffold. Ladders will only be used for gaining access to scaffold; all work will be carried out from the scaffold. An initial inspection and thereafter daily safety checks will be carried out on the scaffold by the site foreman. Where work must be carried out NOT on designated safe platforms such as scaffold etc, then staff must wear approved safety harnesses attached to secure safety lines Where the risk of a fall cannot be eliminated the site manager will ensure suitable safety netting and/or fall protection mattresses are installed prior to allowing work to commence.	6	3	1

Assessors Name	Assessors Signature	Persons Affected By This Risk Assessment
		staff, client staff, other contractors, members of the public

Hazard / Consequences	Control Procedures	Likelihood (a)	Severity (b)	Risk Ranking (= a x b)
	Manned By Installer	9	1	0

Hazard / Consequences	Control Procedures	Likelihood (a)	Severity (b)	Risk Ranking (= a x b)
	Manned By Installer	9	1	0