



Photo 1 – Tree canopies in direct contact with roof of 81 Pinewood Avenue



Photo 2 – Tree canopies in direct contact with roof of 81 Pinewood Avenue



Photo 3 – Tree canopies in direct contact with roof of 81 Pinewood Avenue



Photo 4 – Tree canopies in direct contact with roof of 81 Pinewood Avenue



Photo 5 – T004 (Oak) canopy close to roof of 79 Pinewood Avenue



Photo 6 – Point of previous branch failure in crown of T004 (Oak)



Photo 7 – Previous topping points on T003 & T004 (Oak)



Photo 8 – Structural cracks on building of 81 Pinewood Avenue



Photo 9 – Poor form / topped tree T004



Photo 10 – Poor form / topped tree T003