

From: [REDACTED]
Date: 4 December 2024 at 09:05:48 GMT
To: [REDACTED]
Subject: RE: Photos - 1 of 2

[REDACTED]

Thanks for sending photos over. I would definitely recommend this tree is removed. It seems unlikely that the roots have yet reached underneath the foundations, but they will do if the tree is left to grow.

Given the proximity to the wall, it may be difficult to remove the stump without damaging the wall or its foundations. I would recommend the tree is cut down by a competent tree surgeon and the stump is killed.

I hope that helps? Happy to discuss further if needed.

Kind regards

[REDACTED]

[REDACTED]

WHITE & LLOYD

Consulting Engineers | Building Surveyors | Quantity Surveyors

Our office will be closed for Christmas from Friday 20th December to Monday 6th January.

We would like to wish all our clients and partners a very merry Christmas.




t: +44 (0)208 191 7747 (Switchboard)

e: [REDACTED] | w: www.whiteandlloyd.com

Head Office: Devon House, 11 High Street, Thames Ditton, Surrey, KT7 0SD

Bath Office: 1 Queen Square, Bath. BA1 2HA. t: +44 (0)122 568 3143

Members of and regulated by:



cabe
chartered
association
of building
engineers



CIOB



White & Lloyd Ltd is a limited company registered in England and Wales 9290835.

Help reduce your emissions by not printing this email unless absolutely necessary.

This message and any attachment may contain privileged and confidential information intended for use of the addressees named above. If you are not the intended recipient of this message please notify the sender immediately. You are hereby notified that you should not copy, forward, disclose or otherwise use the message or any part of it in any form whatsoever. If you received this in error, please contact the sender and delete the material from any computer.

From: [REDACTED]
Sent: 03 December 2024 10:32
To: [REDACTED]
Subject: Photos - 1 of 2

[REDACTED]

As per my email last night, please find below a couple of photos of the tree. I've been struggling to send them so I'm sending across a couple of emails. From these photos and your understanding of the foundations, it would be good to understand if you thought the tree could be safely we moved, and in doing so if we would prevent the potential for damage to the next door neighbours foundations in the future.

Please let me know if there's anything else you need.

Many thanks.





Sent from my iPhone