

James Bancroft
SLR Consulting
Broadwalk House
Southernhay West
Exeter
EX1 1GE

Our Ref: SG/2208-07
Your Ref: 422.065540.00001

16 December 2025

Dear James

LAND NORTH OF NEW BATH ROAD, TWYFORD - STAGE 1 ROAD SAFETY AUDIT

I refer to your recent email message regarding the Stage 1 RSA we carried out of this scheme in August 2022. Thank you for sending us the amended drawings, which for ease of reference are as follows:

- 422.065540.00001/PD01 Rev A - Providing 4th Arm to Approved Scheme. 35m ICD Roundabout (Normal), New Bath Road. General Arrangement
- 422.065540.00001/PD01.1 Rev A - Providing 4th Arm to Approved Scheme. Review Undertaken with Reference to DMRB CD 116 Geometric Design of Roundabouts

Only one of the problems raised in 2022 is relevant to this roundabout; namely Problem 2.4, which identified the possibility of parallel circulating and recommended vehicle swept path analysis. The modified design provides a single lane entry from the development arm, thereby eliminating parallel circulating. We note that the lane destination arrows on the other three arms would also discourage parallel circulating (they would need to be updated for the fourth arm).

Accordingly, the proposed scheme revisions do not alter the problems raised by our Stage 1 RSA, nor our associated recommendations. Furthermore, we do not wish to raise any new road safety problems arising from this amendment. Nevertheless, given the change from a split to a single crossing movement for pedestrians on the development arm, we would reiterate the need to maintain good visibility to/from the tactile paving areas.

I trust that the above comments are helpful, but please do let me know if you need anything else.

SLR Consulting

Land North of New Bath Road, Twyford - Stage 1 Road Safety Audit

16 December 2025



Yours sincerely



Steve Giles
Director

email sgiles@gateway-rse.co.uk