




Metal Straps to be removed




Existing presumed mineral wool insulation

Area of boarding to be removed



Mould growth present in almost every roof timber



New timbers which sits above existing ceiling with metal straps connecting to rafter

Existing joists which forms the lath and plaster ceilings

