Verification of application Evidence

Date: 02.11.2026

Applicant Name: Peter Miller

Tree Location: 49 Roslyn Road, Woodley, RG5 3HT

Agent: Al Buchanan BSc (Arboriculture and Tree Management) BA (Hons) MArbor

Aimis Tree Care Limited

TPO: TPO-0003-1951

1. **Tree Identification and Location**

T1 – Cherry

The cherry tree is located immediately adjacent to an existing boundary wall that has sustained damage and requires replacement.

2. **Photographic Evidence**

Photographs are provided to illustrate the existing boundary wall, which has sustained damage and requires replacement.



Aimis Tree Care Limited
Registered in England & Wales No. 10719048
Registered Office: Heath Cottage, Brentmoor Road, Woking, Surrey, GU24 9NE
01483 361158 | info@aimistreecare.co.uk | www.aimistreecare.co.uk



Aimis Tree Care Limited
Registered in England & Wales No. 10719048
Registered Office: Heath Cottage, Brentmoor Road, Woking, Surrey, GU24 9NE
01483 361158 | info@aimistreecare.co.uk | www.aimistreecare.co.uk



Aimis Tree Care Limited
Registered in England & Wales No. 10719048
Registered Office: Heath Cottage, Brentmoor Road, Woking, Surrey, GU24 9NE
01483 361158 | info@aimistreecare.co.uk | www.aimistreecare.co.uk

3. Arboricultural Assessment and Justification

The cherry tree is situated in close proximity to the existing boundary wall, which has sustained damage and requires replacement.

The appointed builder has advised that the wall cannot be repaired or replaced whilst the tree remains in its current position due to the restricted working space and proximity of the stem to the structure.

4. Proposed Works

T1 – Cherry

Fell the tree to ground level to facilitate the replacement of the damaged wall.

5. Declaration Regarding Evidence

The information provided within this application is based upon a visual inspection undertaken by a suitably qualified arboricultural consultant and represents professional arboricultural opinion at the time of inspection.