Tree Code: Sgl/014440

Tree Tag:
Seq No: 6
Position:
Stems: 1
Species: Quercus robur (English Oak)
Site: Barkham Road, Wokingham
Location: Evendons
Grid Ref: SU 79292 67758
OS X/Y: 479291.80, 167757.86
Lat Long: 51.403317, -0.861474
what3words: /// spots.theme.miles
Planted:
Stock Type:
Owner: Wokingham Council
Notes:
Value: £0.00

Felled:	No	**Proposed:**	No
TPO:	Yes	**Private:**	No
WBC School:	No	**None:**	No
Potential:	No	**Confirmed:**	No
Insurance:	No	**Property:**	No
Con Area:	No		



30/10/2026 09:39:

Regimes:



30/10/2026 09:40: Trunk - Ivy/Climber



30/10/2026 09:43: Trunk - Fungus - Fistulina



30/10/2026 09:46: Crown - Low Branches



15/10/2026 09:15:



15/10/2026 09:15:



15/10/2026 09:15:



15/10/2026 09:16:



15/10/2026 09:18:



15/10/2026 09:18:



15/10/2026 09:19: Adjacent - Road



15/10/2026 09:19: Adjacent - Overhead Utilities



15/10/2026 09:19: Target - Footpath



15/10/2026 09:19: Target - Power Cable



15/10/2026 09:20: Target - Road



15/10/2026 09:20: Crown - Major Deadwood >100mm



15/10/2026 09:21: Crown - Thin foliage



15/10/2026 09:21: Crown - Dead Bark



15/10/2026 09:21: Crown - Bark Cracks



15/10/2026 09:22: Crown - Old Pollard



15/10/2026 09:23: Crown - Branch wounds



15/10/2026 09:23: Crown - Branch wounds



17/01/2025 10:01:

Inspection: 30/10/2026

Height: 10 to 15m

Age: Mature

Trunk: 600-750mm

Spread: 05 to 10m

Features:
Adjacent - Road
Adjacent - Overhead Utilities
Growing In - Unmanaged Verge
Target - Footpath
Target - Power Cable
Target - Road

Conditions:
Crown - Bark Cracks
Crown - Branch wounds
Crown - Dead Bark
Crown - Low Branches
Crown - Major Deadwood >100mm
Crown - Old Pollard
Crown - Thin foliage
Trunk - Ivy/Climber
Trunk - Fungus - Fistulina

Comments:

Value: £0.00

Dry Weight: 2,914,654.208 KG

Carbon Weight: 1,457,327.104 KG

CO2 Sequestered: 4,371,981.312 KG (£371,618.41)

CO2 Seq Per Year: 3,875.989 KG (£329.46)

Visited By: Macy Lee

Condition: Fair

CrLightExp: 2 Sides Exposed

Prob of F.: Potentially

Target: High

Deg ofHarm: Severe

SLE: 40 - 80 years

FuncValue:

Cdbh(Auto): < 5.9

Risk: Slight Risk

THREATS: 200

Next Inspection: 10/2029

Recommendations: Remove Deadwood - Fungal fruiting bodies and significant deadwood were observed within the oak tree. The following remedial works are recommended to mitigate the risk of falling branches and reduce the potential hazard to highway users:
1. Remove three large deadwood limbs.
2. Remove broken branches.
3. Remove dead and dying branches exhibiting dieback.

Priority: 12 months

Recom Due Date:

Works:



WOKINGHAM BOROUGH COUNCIL

Overview

Scale	**1: 280**
Date	**17/11/2026**

N
W E
S