Tree Code: Sgl/018453

Tree Tag:

Seq No: 3

Position:

Stems: 1

Species: Quercus robur (English Oak)

Site: Footpath Between Simons Lane And Chestnut Avenue East Of Recreation Ground, Wokingham

Location: Evendons

Grid Ref: SU 78564 69134

OS X/Y: 478563.53, 169133.93

Lat Long: 51.415790, -0.871637

what3words: /// cracks.tolls.mint

Planted:

Stock Type:

Owner: Wokingham Council

Notes:

Value: £0.00

Felled:	No	**Proposed:**	No
TPO:	No	**Private:**	No
CRP - NONE:	Yes	**CRP - FAR:**	No
CPR - PRF:	No	**Insurance:**	No
Property:	No	**Con Area:**	No



29/10/2026 10:31:

Regimes:



29/10/2026 10:31:



29/10/2026 10:32: Growing In - Soil



29/10/2026 10:33: Adjacent - Building - >3m



29/10/2026 10:36: Crown - Branch wounds



29/10/2026 10:36: Crown - Tearout wound



29/10/2026 10:37: Remove Damaged Limb



29/10/2026 10:37: Remove Deadwood



29/10/2026 10:37: Remove Deadwood

Inspection: 29/10/2026

Height: 15 to 20m
Age: Mature
Trunk: 150-300mm
Spread: 05 to 10m
Features: Adjacent - Building - >3m
Growing In - Soil
Conditions: Crown - Branch wounds
Crown - Tearout wound
No significant defects
Comments:

Value: £0.00
Dry Weight: 127,706.338 KG
Carbon Weight: 63,853.169 KG
CO2 Sequestered: 191,559.507 KG (£16,282.56)
CO2 Seq Per Year: 509.482 KG (£43.31)

Visited By: Macy Lee

Condition: Fair
CrLightExp: 4 Sides Exposed
Prob of F.: None apparent
Target: High
Deg ofHarm: Severe
SLE: 40 - 80 years
FuncValue:
Cdbh(Auto): < 5.9
Risk: Insignificant Risk
THREATS: 2.5
Next Inspection: 10/2029
Recommendations: Remove Damaged Limb - remove the dead limb x 2
Remove Deadwood - remove the deadwood x 2
Priority: 12 months
Recom Due Date:
Works:



WOKINGHAM BOROUGH COUNCIL

Overview

Scale	**1: 204**
Date	**30/10/2026**

N
W E
S