

Stowdes Estate Landscape Visual Appraisal

Landscape Appraisal - Character



View southwards from inside plot (near to Wellhouse gate)
No view possible

Stowdes Estate Landscape Visual Appraisal


Landscape Appraisal - Character



Junction of Kenton's Lane & Culham Lane
No view possible

Stowdes Estate Landscape Visual Appraisal

Landscape Appraisal - Character



Public footpath & cricket field by Young's farm
No view possible

Stowdes Estate Landscape Visual Appraisal

Landscape Appraisal - Character



Culham Lane (Upper Culham Farm)
No view possible

Strowdes Estate Landscape Visual Appraisal

Landscape Appraisal - Character



Kenton's Lane

Possible glimpsed view through this existing opening in the hedge in Kenton's Lane. However, proposed new hedging and planting is designed to block this view.

Stowdes Estate Landscape Visual Appraisal

Landscape Appraisal - Character



View from internal estate road (looking north)
No view possible

Stowdes Estate Landscape Visual Appraisal

Landscape Appraisal - Character



View from access point to the most southerly field

The steep contours prevent any possible view of the proposed buildings from this point inside the estate.

Strowdes Estate Landscape Visual Appraisal

Landscape Appraisal - Character



View from inside estate (by gate on Kenton's Lane)

From inside the estate gate a glimpsed view is possible between the trees which line the old track to Templecombe. Proposed planting will remove this view. No possible view from the highway.

Strowdes Estate Landscape Visual Appraisal

Landscape Appraisal - Character



View from Kenton's Lane (former Hatchgate)

No view possible. (The driveway will be removed and the gates replaced with hedging and trees as previously agreed).

Stowdes Estate Landscape Visual Appraisal

Landscape Appraisal - Character



View from Kenton's Lane – near Young's Farm

No view possible either from the road or even from top of the bank.

Stowdes Estate Landscape Visual Appraisal

Landscape Appraisal - Character



View from Kenton's Lane (old Pillar Lodge entrance)

The site is not visible behind trees and hedges. (The gappy boundary hedge is also to be infilled and restored).

Stowdes Estate Landscape Visual Appraisal

Landscape Appraisal - Character



View from inside estate near cedars in SE corner
No views possible due to steep slopes.