

Biodiversity statement

Site address- **11 Strathmore Drive, Charvil, RG10 9QT**

This statement is to check if there are any signs of bats in the void areas of the property.

- During the Measured survey, the roof voids and tile hanging areas were inspected for Presence of bat. The examination revealed no signs of guano or evidence of current or past bat roosts in the roof or wall voids.