

Shinfield garden centre – isolation



RESHAPING THE FUTURE
www.metrodeconstruction.com




Live DB in garden
centre store area

Db's metro asked to be disconnected

 Cable route cable which was
disconnected

Shinfield Garden Centre – Electrical Isolation Evidence Submitted by Metro Deconstruction Services Ltd submitted 11th of July 2025



Shinfield Garden Centre – Electrical Isolation Evidence Submitted by Metro Deconstruction Services Ltd submitted 11th of July 2025

