



Andrew Goodwin
RPP Ltd

SHINFIELD DEMOLITION INSPECTION

Monday, 30th of June 2025

Prepared for LXI Property

Holdings 4 Limited

7 Items Identified

ITEM 1


Heras fencing has been installed with the site welfare compound established



ITEM 2


Skip in place to remove demolition arisings






ITEM 3

View of site looking towards
the retained structure




ITEM 4

Metro site compound




ITEM 5

Demolition Works are underway



ITEM 6

Demolition works progress, the remaining structure is to be removed.



ITEM 7

Demolition works progress photo 2, an excavator can be seen working on site.