

APPENDIX C

PHOTOGRAPHS



Overview of Plot 133 (LEAP visit 29.01.25)



Inspection pit at Plot 133 (LEAP visit 29.01.25)



Overview of Plot 142 (LEAP visit 29.01.25)



Inspection pit at Plot 142 (LEAP visit 29.01.25)



Overview of Plot 141 (LEAP visit 29.01.25)



Inspection pit at Plot 141 (LEAP visit 29.01.25)



Overview of Plot 134, where topsoil was sampled from (LEAP visit 29.01.25)



Inspection Pit excavated by client in Plot 133 (client-provided photograph)



Inspection Pit excavated by client in Plot 133 showing 600mm of clean cover (client-provided photograph)