



Inspection Pit excavated by client in Plot 133 showing 270mm of topsoil(client-provided photograph)



Inspection Pit excavated by client in Plot 141 (client-provided photograph)



Inspection Pit excavated by client in Plot 141 showing 630mm of clean cover and 160mm of topsoil (client-provided photograph)



Inspection Pit excavated by client in Plot 142 showing 600mm of clean cover (client-provided photograph)



Inspection Pit excavated by client in Plot 133 showing 220mm of topsoil(client-provided photograph)



Photograph provided by the client of Plot 133 on completion and placement of topsoil



Photograph provided by the client of Plot 141 on completion and placement of topsoil



Photograph provided by the client of Plot 142 on completion and placement of topsoil



Photograph provided by the client of Plot 133 on placement and clearance of subsoil, prior to topsoil placement



Photograph provided by the client of Plot 141 on placement and clearance of subsoil, prior to topsoil placement



Photograph provided by the client of Plot 142 on placement and clearance of subsoil, prior to topsoil placement