



01: SIDE VIEW OF SELF SOWN TREE (T-01 )+ DAMAGE TO FACE OF PULHAMITE



02: FRON VIEW OF SELF SOWN TREE (T-01 ) + DAMAGE TO FACE OF PULHAMITE



03: POLE (STEM) OF T-02 LEANING INTO T-01



04: POLES (STEMS) & STOOL OF T-02 (WILL BE UNBLANCED IS ONLY ONE REMOVED)



05: TREE T-03 FALLEN ACROSS PATH & NOW RESTING ON PULHAMITE



06: TREE T-03 FALLEN ACROSS PATH & NOW RESTING ON PULHAMITE