

Photographic Log

Client Name: Wrenbridge Land Ltd		Site Location: Shinfield Park, Reading	Project No.: 610344.0000.0000
Photo No. 3	Date 11 th June 2024		
Description: Back up generator in basement plant room			

Photographic Log

Client Name: Wrenbridge Land Ltd		Site Location: Shinfield Park, Reading	Project No.: 610344.0000.0000
Photo No. 4	Date 11 th June 2024		
Description: Back up generator in ground floor plant room			

Photo No.	Date	
5	11 th June 2024	
Description: Ground floor plant and control room		

Photographic Log

Client Name:		Site Location:	Project No.:
Wrenbridge Land Ltd		Shinfield Park, Reading	610344.0000.0000
Photo No.	Date		
6	11 th June 2024		
Description: External view of office facility and access road			

Photographic Log

Client Name:		Site Location:	Project No.:
Wrenbridge Land Ltd		Shinfield Park, Reading	610344.0000.0000
Photo No.	Date		
7	11 th June 2024		
Description: View of former council garages to the north of the main office building. Existing woodland beyond.			

Photo No.	Date		
8	11 th June 2024		
Description: Ventilation to main office building plant cooling system on northern elevation of building.			

Photographic Log

Client Name:		Site Location:	Project No.:
Wrenbridge Land Ltd		Shinfield Park, Reading	610344.0000.0000
Photo No.	Date		
9	11 th June 2024		
Description: Walkway around main office building on western elevation.			
Photo No.	Date		
10	11 th June 2024		
Description: Walkway and leisure area on western elevation adjacent to the pond.			

Photographic Log

Client Name:		Site Location:	Project No.:
Wrenbridge Land Ltd		Shinfield Park, Reading	610344.0000.0000
Photo No.	Date		
11	11 th June 2024		
Description: View of pond on western elevation of main office building			

Photo No.	Date		
12	11 th June 2024		
Description: View of main office building with ramp access to car parking and cycleway			

