



Matthew Brearley
RPP Ltd

SHINFIELD DEMOLITION INSPECTION

Thursday, 17th of July 2025

Prepared for LXI Property

Holdings 4 Limited

7 Items Identified



ITEM 1

Demolition of the greenhouse structure is complete with compacted type 1 aggregate infills used to leave a level finish.




ITEM 2

Completed site sign in sheet.



ITEM 3

Broken glass to be removed and
type 1 layer to be installed
(scheduled for the 18th of July)



ITEM 4

Hoarding (photo taken from within
the structure)



ITEM 5

View of the
demolition area following the
works



ITEM 6

View Of site (photo 2)



ITEM 7

Car park to be jet washed
(scheduled for the 18th of July)