



A large part of the site was a dense mixed woodland, therefore individual trees were unable to be surveyed. Therefore Edges of woodlands were shown and in open areas, separate trees were surveyed. The whole site was an *ex-novo* *salix* *maritima* forest.

CR	Earth Road	S	Stamp
<u>ON FENCES/WALLS/DIVISIONS</u>			
S/W	Borers Wire Fence	S/W	Safety Fence
C/B	Grass Barrier	S/W	Steel Railings
C/B	Close Border Fence	S/W	Steel High Fence
C/I	Corrugated Iron Fence	W	Wooden Fence
C/L	Chain Link Fence	W	Brick Wall
FP2	Paved / Board Fence	C	Concrete wall
W/C	Wattle Rail	W	Concrete Picket Wall
C/B	Iron Rail Fence	R/W	Retaining Wall

[illegible]

www.design-base.co.uk

File Name:
Db1911-topo And Sections

Client:	Date
David Bates	13/05/2016
Contact:	Scale

Grid Orientation: North GPS	Site Level Datum OS GPS
--------------------------------	----------------------------

All dimensions are to be checked on site where applicable. This drawing must not be scaled, and only written dimensions should be respected.