

Site Inspection Report



Job No 1025
Job Name Orchards Paddock

Contractor AH Building Contractors
Date of Inspection 21st July 2026
Weather conditions noted Hot sunny
Purpose of visit Determine sub-surface route for surface water drainage

The Byre Lantern Courtyard
The Street Bramley
Hampshire RG26 5DE

T 01256 587 888
E studio@morsewebb.co.uk
W morsewebb.co.uk

Present	Name	Title	Company
AH MWA	Adrian Williams David Holford- Wright	Director Project Architect	AH Building Contractors Morse Webb Architects

No	Item	% Complete or actions
1	Stage of Works on Site	
1.1	Pre-Commencement	
2	Items Inspected and Discussed (observations)	
2.1	Determine potential sub-surface route for surface water drainage, following concerns raised by Planning Authorities Ecologist.	
3	Unsatisfactory Work Identified / Resolution Required (actions)	
3.1	N/A	
4	General Issues / Requests for Information	
4.1	Proposed sub-surface route illustrated on Orange Key Drawing 25048/501 sd – Site Plan Showing SUDS Drainage Strategy illustrates Main Surface Water drain to pond passing close to existing tree boles (trunks). AH had laid hose along approximate route of	
5	Variations/Substitutions/Instructions	
5.1	N/A	
6	Distribution	
6.1	Client, Contractor, Structural Engineer, Planning	

Progress photos - File location (1025-Photos-Annotated-260721)