




**CCTV REPORT FOR: WEST WOOD
LOWER WOKINGHAM ROAD
CROWTHORNE
BERKSHIRE
RG45 6BY**

CONTENTS: SITE LAYOUT
FOUNDATION RECORD
PHOTOGRAPHS
ROOT IDENTIFICATION



Client: 360GlobalNet
Regus House
Herald Way
Pegasus Business Park
Castle Donnington
DE74 2TZ

Insured:
Reference:



1st Site Visit: 02-Dec-22
1st Report Date: 15-Mar-23

2nd Site Visit: 14-Jun-23
2nd Report Date: 28-Jun-23

The Drainage Repair Company Ltd | Office 6 | Unit 14/4 Station Road | Coleshill | Birmingham | B46 1HT

Telephone: 01530 272 349 **Email:** info@thedrainagerepaircompany.com

Registered in England & Wales Number: 08570351 | Registered Office: Bourne House, 475 Godstone Road, Whyteleafe, Surrey, CR3 0BL

www.thedrainagerepaircompany.com




Drainage
Repair Company

SITE LAYOUT

Site Crew: TLR / DJ

Date: 02-Dec-22



FRONT

(This plan is not to be scaled and is provided to illustrate general layout only)

General Comments:

Note: Runs shown in red have been adopted by the local water authority.

Key :

= Storm Gully	= Storm Pipe	= Foul Gully	= W/C or Soil Pipe	= Inspection Chamber
= Rodding Eye	= Surveyed pipe indicating flow	= Unsurveyed pipe		
= Exploratory Hole (hand dug pit and/or hand auger)	= Boundary line			
= Hedges & Shrubs	= Trees & bushes	= Area of damage		

Address: **WEST WOOD, LOWER WOKINGHAM ROAD, CROWTHORNE, BERKSHIRE, RG45 6BY**





Root identification
Vegetation surveys
Tree/Building investigations
Plant taxonomy

Richardson's Botanical Identifications

The Drainage Repair Company
Suite 15, Leatherline House
71 Narrow Lane
AYLESTONE
Leicester LE2 8NA

28/06/2023

Dr Ian B K Richardson
BSc, MSc, PhD, MRSB, FLS
James Richardson
BSc (Hons. Biology)

Enterprise House
49-51 Whiteknights Road
Reading
RG6 7BB

Tel: (0118) 986 9552 *(Direct line)*
E-mail: richardsons@botanical.net
Web: www.botanical.net

Your ref: **Root ID**

Our ref: 87/0606

Dear Sirs

West Wood, Crowthorne, Berks RG45 6BY

The samples you sent in relation to the above on 20/06/2023 have been examined. Their structures were referable as follows:

TP1, 1.6-2.5m		
3 no.	Examined root: most referable to QUERCUS (Oak).	Dead*.
4 no.	All pieces of BARK only - not enough material for identification.	
25 no.	Unfortunately all with insufficient cells for identification.	

Click here for more information: [QUERCUS](#)

I trust this is of help. Please call us if you have any queries; our Invoice is enclosed.

Yours faithfully



Dr Ian B K Richardson

* Based mainly on the Iodine test for starch. Starch is present in some cells of a living woody root, but is more or less rapidly broken down by soil micro-organisms on death of the root, sometimes before decay is evident. This result need not reflect the state of the parent tree.

** Try out our web site on www.botanical.net **