

HSEQ Inspection ()

Today date: 22/08/2025 11:32



General Details

Date Submitted	Inspector	Job Reference	Job ID
14/08/2025 11:11	Chris Rowden		N/A
Depot Name	Inspection	Subcontractor	Points
N/A	Tree Cutting Request	Customer Field Operations	1/1
Depot Manager Name	Score Percentage	Inspection Status	Contract
N/A	100%	Acceptable	Other
Contract Manager	Contract Number		
N/A	N/A		
Location			
S1364351			
Supervisors			
Chris Rowden			

Tree Cutting Request Inspection			
100.00%	1/1	100.00%	3/3
100.00%	4/4	100.00%	2/2
Total			100.00%

Depotnet HSEQ Audit - please email enquires@depotnet.co.uk for further details

1 Please select which region you are in?

Points: 0

South

1 Please give a detailed summary of the issue and possibly solution.

Points: 0

2 x large trees in los need trimming back. could use current drops as a feed

2 Is the pole effected by the tree a Joint User Pole?(JUP)

No

Points: 0

3 Are there any special requirements or conditions that would need to be considered when carrying out tree cutting?

No

Points: 1

1 Please upload a photo of the pole.

Points: 0



Points: 0



Points: 0



4 Please upload a photo depicting a suitable position for the bracket on the house.

Points: 0




1 Was the person who owns the tree in at the time of the survey ?

No

Points: 0

2 Surveyor Signature Sign Off.



Points: 0