






© Crown Copyright. All Rights Reserved. License Number 100022432.

Envirocheck®

LANDMARK INFORMATION GROUP®

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Map ID
- Several of Type at Location


Agency and Hydrological (Boreholes)

- BGS Borehole Depth 0 - 10m
- BGS Borehole Depth 10 - 30m
- BGS Borehole Depth 30m +
- Confidential
- Other

For Borehole information please refer to the Borehole .csv file which accompanied this slice.

A copy of the BGS Borehole Ordering Form is available to download from the Support section of www.envirocheck.co.uk.

Borehole Map - Slice A



Order Details


Order Number: 297188414_1_1
Customer Ref: E28112
National Grid Reference: 476160, 166300
Slice: A
Site Area (Ha): 18.12
Search Buffer (m): 1000

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ

Landmark®
INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown Copyright. All Rights Reserved. License Number 100022432.

Envirocheck®

LANDMARK INFORMATION GROUP®

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point


OS Water Network Data

- | | |
|--------------|-------------------------|
| Canal | Drain |
| Reservoir | Other |
| Foreshore | Lake |
| Marsh | Transfer |
| Tidal River | Lock Or Flight Of Locks |
| Inland River | Sea |

Contours (height in meters)

- Standard Contour 105 100 95
- Master Contour
- Spot Height 167.3
- MLW Mean Low Water
- MHW Mean High Water

OS Water Network Map - Slice A



Order Details


Order Number: 297188414_1_1
Customer Ref: E28112
National Grid Reference: 476160, 166300
Slice: A
Site Area (Ha): 18.12
Search Buffer (m): 1000

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ

Landmark®
INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point

Risk of Flooding from Surface Water


- High - 30 Year Return
- Medium - 100 Year Return
- Low - 1000 Year Return

Suitability

See the suitability map below

- National to county
- County to town
- Town to street
- Street to parcels of land
- Property

EA/NRW Suitability Map - Slice A




Order Details

Order Number: 297188414_1_1
Customer Ref: E28112
National Grid Reference: 476160, 166300
Slice: A
Site Area (Ha): 18.12
Search Buffer (m): 1000

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ




© Crown Copyright. All Rights Reserved. License Number 100022432.


General

Specified Site Specified Buffer(s) Bearing Reference Point

Estimated Soil Chemistry Arsenic



Estimated Soil Chemistry Arsenic - Slice A



Order Details

Order Details: 297188414_1_1
Customer Ref: E28112
National Grid Reference: 476160, 166300
Slice: A
Site Area (Ha): 18.12
Search Buffer (m): 1000

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ




© Crown Copyright. All Rights Reserved. License Number 100022432.


General

Specified Site Specified Buffer(s) Bearing Reference Point

Estimated Soil Chemistry Cadmium



Estimated Soil Chemistry Cadmium - Slice A




Order Details

Order Details: 297188414_1_1
Customer Ref: E28112
National Grid Reference: 476160, 166300
Slice: A
Site Area (Ha): 18.12
Search Buffer (m): 1000

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ




© Crown Copyright. All Rights Reserved. License Number 100022432.


General

Specified Site Specified Buffer(s) Bearing Reference Point

Estimated Soil Chemistry Lead



Estimated Soil Chemistry Lead - Slice A



Order Details

Order Details: 297188414_1_1
Customer Ref: E28112
National Grid Reference: 476160, 166300
Slice: A
Site Area (Ha): 18.12
Search Buffer (m): 1000

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ




© Crown Copyright. All Rights Reserved. License Number 100022432.

General


Specified Site Specified Buffer(s) Bearing Reference Point

Estimated Soil Chemistry Nickel

Nickel Concentrations mg/kg



Estimated Soil Chemistry Nickel - Slice A




Order Details

Order Details: 297188414_1_1
Customer Ref: E28112
National Grid Reference: 476160, 166300
Slice: A
Site Area (Ha): 18.12
Search Buffer (m): 1000

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ



Index Map

For ease of identification, your site and buffer have been split into Slices, Segments and Quadrants. These are illustrated on the Index Map opposite and explained further below.

Slice

Each slice represents a 1:10,000 plot area (2.7km x 2.7km) for your site and buffer. A large site and buffer may be made up of several slices (represented by a red outline), that are referenced by letters of the alphabet, starting from the bottom left corner of the slice "grid". This grid does not relate to National Grid lines but is designed to give best fit over the site and buffer.

Segment

A segment represents a 1:2,500 plot area. Segments that have plot files associated with them are shown in dark green, others in light blue. These are numbered from the bottom left hand corner within each slice.

Quadrant

A quadrant is a quarter of a segment. These are labelled as NW, NE, SW, SE and are referenced in the datasheet to allow features to be quickly located on plots. Therefore a feature that has a quadrant reference of A7NW will be in Slice A, Segment 7 and the NW Quadrant.

A selection of organisations who provide data within this report:



Envirocheck reports are compiled from 136 different sources of data.

Client Details

Mr J Perkins, EMS (Environmental Management Solutions), Sigeric Business Park, Holme Lacy Road, Hereford, Herefordshire, HR2 6BQ

Order Details


Order Number: 294110078_1_1
Customer Ref: E28112
National Grid Reference: 476150, 166280
Site Area (Ha): 18.12
Search Buffer (m): 1000

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ

Full Terms and Conditions can be found on the following link:
<http://www.landmarkinfo.co.uk/Terms/Show/515>

Appendix F – Landmark Envirocheck - Mining and Ground Stability Report



© Crown Copyright. All Rights Reserved. License Number 100022432.

Envirocheck[®]

LANDMARK INFORMATION GROUP[®]

Ground Stability Data (1:50,000)

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Slice
- Map ID


Potential for Landslide Ground Stability Hazards

- High
- Moderate
- Low
- Very Low

Potential for Ground Dissolution Stability Hazards

- High
- Moderate
- Low
- Very Low

Mining and Ground Stability - Slice A



Order Details


Order Number: 294110078_1_1
 Customer Ref: E28112
 National Grid Reference: 476160, 166300
 Slice: A
 Site Area (Ha): 18.12
 Search Buffer (m): 1000

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ

Landmark[®]
 LANDMARK INFORMATION GROUP

Tel: 0844 844 9952
 Fax: 0844 844 9951
 Web: www.envirocheck.co.uk



© Crown Copyright. All Rights Reserved. License Number 100022432.

Envirocheck®

LANDMARK INFORMATION GROUP®

Ground Stability Data (1:50,000)

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Slice
- Map ID


Potential for Running Sand Ground Stability Hazards

- High
- Moderate
- Low
- Very Low

Potential for Shrinking or Swelling Clay Ground Stability Hazards

- High
- Moderate
- Low
- Very Low

Mining and Ground Stability - Slice A



Order Details

Order Number: 294110078_1_1
 Customer Ref: E28112
 National Grid Reference: 476160, 166300
 Slice: A
 Site Area (Ha): 18.12
 Search Buffer (m): 1000

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ

Landmark®
 LANDMARK INFORMATION GROUP

Tel: 0844 844 9952
 Fax: 0844 844 9951
 Web: www.envirocheck.co.uk

Envirocheck[®] Report:

Mining and Ground Stability Datasheet

Order Details:

Order Number:

294110078_1_1

Customer Reference:

E28112

National Grid Reference:

476160, 166300

Slice:

A

Site Area (Ha):

18.12

Search Buffer (m):

1000

Site Details:

Ducks Nest Farm, Eversley Road

Arborfield Cross

READING

RG2 9PJ

Client Details:

Mr J Perkins

EMS (Environmental Management Solutions)

Sigeric Business Park

Holme Lacy Road

Hereford

Herefordshire

HR2 6BQ

Report Section and Details	Page Number
Summary	-
The Summary section provides an overview of the data contained within the report, detailing the number of data set features or the existence of a data set in relation to the buffer selected. For ease of reference, the report is broken down into 4 sections of data; Mining and Natural Cavities Data, Historical Land Use Information (1:2,500), Historical Land Use Information (1:10,000) and Ground Stability Data (1:50,000).	
Mining and Natural Cavities Data	1
The Mining and Natural Cavities Data section features data sets related to the existence of mining areas and their potential hazards; and details of naturally formed cavities. Data sets within this section are not plotted, with the exception of BGS Recorded Mineral Sites and Potential Mining Areas which feature on the Historical Land Use Information (1:10,000) map.	
Historical Land Use Information (1:2,500)	2
The Historical Land Use Information (1:2,500) section contains data captured from analysis carried out by Landmark of 1:1,250 and 1:2,500 scale historical Ordnance Survey mapping, identifying areas where, historically, the land uses were potentially contaminative. For the purpose of this Envirocheck module, only historical data relating to mining and ground stability has been included and plotted on the corresponding Historical Land Use Information (1:2,500) map. This section also includes the Subterranean Features data set, which details various man-made and man-used underground spaces obtained from the Subterranea Britannica society.	
Historical Land Use Information (1:10,000)	3
The Historical Land Use (1:10,000) section covers data captured from the systematic analysis carried out by Landmark of 1:10, 560 and 1:10,000 scale historical Ordnance Survey mapping dating back to the mid-19th century, identifying potentially contaminative past industrial land uses. For the purpose of this Envirocheck module, only data relating to mining and ground stability has been included and plotted on the accompanying Historical Land Use Information (1:10,000) map.	
Ground Stability Data (1:50,000)	4
The Ground Stability (1:50,000) section includes the BGS Geosure data suite, reporting features to 250m and plotted onto 3 separate maps. Also reported is brine subsidence, brine mining and salt mining data sets, of which Brine Pumping and Salt Mining Related Features are plotted, and subsidence insurance claims and insurance investigations data, which is not plotted.	
Historical Map List	5
The Historical Map List section details the historical mapping that has been analysed for your site, in relation to the Historical Land Use Information sections.	
Data Currency	6
Data Suppliers	7
Useful Contacts	8

Copyright Notice

© Landmark Information Group Limited 2022. The Copyright on the information and data and its format as contained in this Envirocheck® Report ("Report") is the property of Landmark Information Group Limited ("Landmark") and several other Data Providers, including (but not limited to) Ordnance Survey, British Geological Survey, and the Environment Agency/Natural Resources Wales, and must not be reproduced in whole or in part by photocopying or any other method. The Report is supplied under Landmark's Terms and Conditions accepted by the Customer. A copy of Landmark's Terms and Conditions can be found with the Index Map for this report. Additional copies of the Report may be obtained from Landmark, subject to Landmark's charges in force from time to time. The Copyright, design rights and any other intellectual rights shall remain the exclusive property of Landmark and /or other Data providers, whose Copyright material has been included in this Report.

© Copyright Stantec UK Limited. All rights reserved.

The brine subsidence data relating to the Droitwich area as provided in this report is derived from JPB studies and physical monitoring undertaken annually over more than 35 years. For more detailed interpretation contact enquiries@jpb.co.uk. JPB retain the copyright and intellectual rights to this data and accept no liability for any loss or damage, including in direct or consequential loss, arising from the use of this data.

The Mining Instability data was obtained on licence from Ove Arup & Partners Limited (for further information, contact mining.review@arup.com). No reproduction or further use of such Data is to be made without the prior written consent of Ove Arup & Partners Limited. The supplied Mining Instability data is derived from publicly available records and other third party sources and neither Ove Arup & Partners nor Landmark warrant the accuracy or completeness of such information or data.

Report Version v53.0

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m
Mining and Natural Cavities Data					
BGS Recorded Mineral Sites	pg 1		1		1
Coal Mining Affected Areas			n/a	n/a	n/a
Man Made Mining Cavities					
Mining Instability			n/a	n/a	n/a
Natural Cavities					
Non Coal Mining Areas of Great Britain				n/a	n/a
Potential Mining Areas					
Historical Land Use Information (1:2,500)					
Extractive Industries or Potential Excavations from 1855-1909 (100m)				n/a	n/a
Extractive Industries or Potential Excavations from 1893-1915 (100m)				n/a	n/a
Extractive Industries or Potential Excavations from 1906-1937 (100m)				n/a	n/a
Extractive Industries or Potential Excavations from 1924-1949 (100m)				n/a	n/a
Extractive Industries or Potential Excavations from 1950-1980 (100m)	pg 2		4	n/a	n/a
Subterranean Features (100m)				n/a	n/a
Historical Land Use Information (1:10,000)					
Air Shafts					
Disturbed Ground					
General Quarrying					
Heap, unknown constituents					
Mineral Railway					
Mining & quarrying general					
Mining of coal & lignite					
Quarrying of sand & clay, operation of sand & gravel pits					
Former Marshes					
Potentially Infilled Land (Non-Water)	pg 3		1		
Potentially Infilled Land (Water)	pg 3				1
Ground Stability Data (1:50,000)					
CBSCB Compensation District			n/a	n/a	n/a
Brine Pumping Related Features					
Brine Subsidence Solution Area					
Potential for Collapsible Ground Stability Hazards	pg 4	Yes		n/a	n/a
Potential for Compressible Ground Stability Hazards	pg 4	Yes		n/a	n/a
Potential for Ground Dissolution Stability Hazards	pg 4	Yes		n/a	n/a
Potential for Landslide Ground Stability Hazards	pg 4	Yes		n/a	n/a
Potential for Running Sand Ground Stability Hazards	pg 4	Yes		n/a	n/a
Potential for Shrinking or Swelling Clay Ground Stability Hazards	pg 4	Yes		n/a	n/a
Salt Mining Related Features					

Report Version v53.0

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
1	BGS Recorded Mineral Sites Site Name: Targets Farm Brick Field Location: Arborfield Garrison, Wokingham, Berkshire Source: British Geological Survey, National Geoscience Information Service Reference: 145851 Type: Opencast Status: Ceased Operator: Unknown Operator Operator Location: Not Supplied Periodic Type: Palaeogene Geology: London Clay Formation Commodity: Common Clay and Shale Positional Accuracy: Located by supplier to within 10m	A7NE (E)	98	1	476486 166210
2	BGS Recorded Mineral Sites Site Name: Whitehall Location: Arborfield, Reading, Berkshire Source: British Geological Survey, National Geoscience Information Service Reference: 10635 Type: Opencast Status: Ceased Operator: Unknown Operator Operator Location: Not Supplied Periodic Type: Palaeogene Geology: London Clay Formation Commodity: Common Clay and Shale Positional Accuracy: Located by supplier to within 10m	A3SW (S)	774	1	476386 165219
	Coal Mining Affected Areas In an area which may not be affected by coal mining				
	Non Coal Mining Areas of Great Britain No Hazard				

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
3	Extractive Industries or Potential Excavations from 1950-1980 Use: Pond First Map Published 1968 Date: Last Map Published N/A Date:	A11SW (E)	30	-	476352 166311
4	Extractive Industries or Potential Excavations from 1950-1980 Use: Pond First Map Published 1968 Date: Last Map Published N/A Date:	A11SW (NE)	58	-	476400 166419
5	Extractive Industries or Potential Excavations from 1950-1980 Use: Pond First Map Published 1968 Date: Last Map Published N/A Date:	A7NW (SE)	75	-	476455 166084
6	Extractive Industries or Potential Excavations from 1950-1980 Use: Pond First Map Published 1967 Date: Last Map Published N/A Date:	A10SE (NW)	78	-	475862 166433

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
7	Potentially Infilled Land (Non-Water) Use: Unknown Filled Ground (Pit, quarry etc) Date of Mapping: 1990	A7NW (E)	70	-	476453 166228
8	Potentially Infilled Land (Water) Use: Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Date of Mapping: 1932	A8SW (SE)	577	-	476893 165851

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	CBSCB Compensation District The site does not fall within the brine compensation area.				
	Brine Subsidence Solution Area The site does not fall within the brine subsidence solution area.				
9	Potential for Collapsible Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A7NW (NW)	0	1	476163 166300
	Potential for Compressible Ground Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A7NW (NW)	0	1	476163 166300
	Potential for Ground Dissolution Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A7NW (NW)	0	1	476163 166300
10	Potential for Landslide Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A7NW (NW)	0	1	476163 166300
11	Potential for Running Sand Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A10SE (W)	0	1	475967 166354
12	Potential for Running Sand Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A7NW (NW)	0	1	476163 166300
13	Potential for Running Sand Ground Stability Hazards Hazard Potential: Low Source: British Geological Survey, National Geoscience Information Service	A10SE (NW)	0	1	476057 166358
14	Potential for Shrinking or Swelling Clay Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A10SE (W)	0	1	475967 166354
15	Potential for Shrinking or Swelling Clay Ground Stability Hazards Hazard Potential: Low Source: British Geological Survey, National Geoscience Information Service	A7NW (NW)	0	1	476163 166300
	Potential for Shrinking or Swelling Clay Ground Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A10SE (NW)	0	1	476057 166358

The following mapping has been analysed for Historical Land Use Information (1:2,500):

1:2,500	Mapsheet	Published Date
Ordnance Survey Plan	SU7566	1967
Ordnance Survey Plan	SU7566	1967
Ordnance Survey Plan	SU7565	1968
Ordnance Survey Plan	SU7665	1968
Ordnance Survey Plan	SU7665	1968
Ordnance Survey Plan	SU7666	1968
Ordnance Survey Plan	SU7666	1968
Ordnance Survey Plan	SU7666	1968
Ordnance Survey Plan	SU7666	1968

The following mapping has been analysed for Historical Land Use Information (1:10,000):


1:10,560	Mapsheet	Published Date
Berkshire	046_00	1876
Hampshire & Isle Of Wight	005_00	1877
Berkshire	037_00	1883
Berkshire	038_00	1883
Berkshire	037_SE	1900
Berkshire	038_SW	1900
Berkshire	045_NE	1900
Berkshire	046_NW	1900
Berkshire	038_SW	1912
Berkshire	046_NW	1912
Berkshire	037_SE	1913
Berkshire	045_NE	1913
Berkshire	038_SW	1931
Berkshire	046_NW	1932
Ordnance Survey Plan	SU76NE	1961
Ordnance Survey Plan	SU76NW	1961
Ordnance Survey Plan	SU76SE	1961
Ordnance Survey Plan	SU76SW	1961
1:10,000	Mapsheet	Published Date
Ordnance Survey Plan	SU76SE	1978
Ordnance Survey Plan	SU76SW	1984
Ordnance Survey Plan	SU76NE	1990
Ordnance Survey Plan	SU76NW	1990

Mining and Cavities Data	Version	Update Cycle
BGS Recorded Mineral Sites British Geological Survey - National Geoscience Information Service	November 2021	Bi-Annually
Coal Mining Affected Areas The Coal Authority - Property Searches	March 2014	Annual Rolling Update
Man Made Mining Cavities Stantec UK Ltd	December 2021	Bi-Annually
Mining Instability Ove Arup & Partners	June 1998	Not Applicable
Natural Cavities Stantec UK Ltd	December 2021	Bi-Annually
Non Coal Mining Areas of Great Britain British Geological Survey - National Geoscience Information Service	May 2015	Not Applicable
Historical Land Use Information (1:2,500)	Version	Update Cycle
Subterranean Features Landmark Information Group Limited	February 2020	Bi-Annually
Ground Stability Data (1:50,000)	Version	Update Cycle
CBSCB Compensation District Cheshire Brine Subsidence Compensation Board (CBSCB) Cheshire Brine Subsidence Compensation Board (CBSCB)	August 2011 November 2020	As notified
Potential for Collapsible Ground Stability Hazards British Geological Survey - National Geoscience Information Service	April 2020	As notified
Potential for Compressible Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Potential for Ground Dissolution Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Potential for Landslide Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Potential for Running Sand Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Potential for Shrinking or Swelling Clay Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	As notified
Brine Subsidence Solution Area Johnson Poole & Bloomer	December 2020	Annual Rolling Update

A selection of organisations who provide data within this report

Data Supplier	Data Supplier Logo
Ordnance Survey	
British Geological Survey	 British Geological Survey NATURAL ENVIRONMENT RESEARCH COUNCIL
The Coal Authority	 The Coal Authority
Ove Arup	
Stantec UK Ltd	
Wardell Armstrong	 wardell armstrong your earth our world
Johnson Poole & Bloomer	

Contact	Name and Address	Contact Details
1	British Geological Survey - Enquiry Service British Geological Survey, Environmental Science Centre, Keyworth, Nottingham, Nottinghamshire, NG12 5GG	Telephone: 0115 936 3143 Fax: 0115 936 3276 Email: enquiries@bgs.ac.uk Website: www.bgs.ac.uk
-	Landmark Information Group Limited Imperium, Imperial Way, Reading, Berkshire, RG2 0TD	Telephone: 0844 844 9952 Fax: 0844 844 9951 Email: customerservices@landmarkinfo.co.uk Website: www.landmarkinfo.co.uk



© Crown Copyright. All Rights Reserved. License Number 100022432.

Envirocheck®

LANDMARK INFORMATION GROUP®

Historical Land Use Information (1:2,500)

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Map ID
- Several of Type at Location


Potentially Contaminative Industrial Uses (Extractive Industries Activity)

	Point	Line	Polygon
Extractive Industries Activity from 1855 - 1909	▲	—	■
Extractive Industries Activity from 1893 - 1915	▲	—	■
Extractive Industries Activity from 1906 - 1937	▲	—	■
Extractive Industries Activity from 1924 - 1949	▲	—	■
Extractive Industries Activity from 1950 - 1980	▲	—	■

Subterranean Features

	Point	Line	Polygon
Subterranean Features	▼	---	■

Mining and Ground Stability - Segment A6



Order Details


Order Number: 294110078_1_1
Customer Ref: E28112
National Grid Reference: 476160, 166300
Slice: A
Site Area (Ha): 18.12
Plot Buffer (m): 100

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ

Landmark®
INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



Envirocheck®

● LANDMARK INFORMATION GROUP®

Historical Land Use Information (1:2,500)

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Map ID
- Several of Type at Location


Potentially Contaminative Industrial Uses (Extractive Industries Activity)

	Point	Line	Polygon
Extractive Industries Activity from 1855 - 1909	▲	—	■
Extractive Industries Activity from 1893 - 1915	▲	—	■
Extractive Industries Activity from 1906 - 1937	▲	—	■
Extractive Industries Activity from 1924 - 1949	▲	—	■
Extractive Industries Activity from 1950 - 1980	▲	—	■

Subterranean Features

	Point	Line	Polygon
Subterranean Features	▼	---	■

Mining and Ground Stability - Segment A7



Order Details


Order Number: 294110078_1_1
Customer Ref: E28112
National Grid Reference: 476160, 166300
Slice: A
Site Area (Ha): 18.12
Plot Buffer (m): 100

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ

Landmark
● INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown Copyright. All Rights Reserved. License Number 100022432.

Envirocheck®

LANDMARK INFORMATION GROUP®

Historical Land Use Information (1:2,500)

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Map ID
- Several of Type at Location


Potentially Contaminative Industrial Uses (Extractive Industries Activity)

	Point	Line	Polygon
Extractive Industries Activity from 1855 - 1909	▲	—	■
Extractive Industries Activity from 1893 - 1915	▲	—	■
Extractive Industries Activity from 1906 - 1937	▲	—	■
Extractive Industries Activity from 1924 - 1949	▲	—	■
Extractive Industries Activity from 1950 - 1980	▲	—	■

Subterranean Features

	Point	Line	Polygon
Subterranean Features	▼	---	■

Mining and Ground Stability - Segment A10



Order Details


Order Number: 294110078_1_1
Customer Ref: E28112
National Grid Reference: 476160, 166300
Slice: A
Site Area (Ha): 18.12
Plot Buffer (m): 100

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ

Landmark®
INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown Copyright. All Rights Reserved. License Number 100022432.

Envirocheck®

LANDMARK INFORMATION GROUP®

Historical Land Use Information (1:2,500)

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Map ID
- Several of Type at Location


Potentially Contaminative Industrial Uses (Extractive Industries Activity)

	Point	Line	Polygon
Extractive Industries Activity from 1855 - 1909	▲	—	■
Extractive Industries Activity from 1893 - 1915	▲	—	■
Extractive Industries Activity from 1906 - 1937	▲	—	■
Extractive Industries Activity from 1924 - 1949	▲	—	■
Extractive Industries Activity from 1950 - 1980	▲	—	■

Subterranean Features

	Point	Line	Polygon
Subterranean Features	▼	---	■

Mining and Ground Stability - Segment A11



Order Details

Order Number: 294110078_1_1
Customer Ref: E28112
National Grid Reference: 476160, 166300
Slice: A
Site Area (Ha): 18.12
Plot Buffer (m): 100

Site Details

Ducks Nest Farm, Eversley Road, Arborfield Cross, READING, RG2 9PJ

Landmark®
INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk

Environmental Management Solutions Ltd.
The Old Surgery,
22a King Street,
Hereford
HR4 9DA

Email: enquiries@ems-geotech.co.uk
Tel. 01432 263333 Fax. 01432 263355