


HSEQ Inspection (Wo-02623408)

Today date: 01/05/2025 09:23



General Details

Date Submitted	Inspector	Job Reference	Job ID
01/05/2025 09:07	Alan Hutton	Wo-02623408	N/A
Depot Name	Inspection	Subcontractor	Points
N/A	Tree Cutting Request	Customer Field Operations	1/1
Depot Manager Name	Score Percentage	Inspection Status	Contract
N/A	100%	Acceptable	
Contract Manager	Contract Number		
N/A	N/A		
Location			
107 Oxford Rd, Berkshire, RG41 2YN			

Tree Cutting Request Inspection			
100.00%	1/1	100.00%	3/3
100.00%	4/4	100.00%	2/2
Total			100.00%

Depotnet HSEQ Audit - please email enquires@depotnet.co.uk for further details

1 Please select which region you are in?

Points: 0

Midlands

1 Please give a detailed summary of the issue and possibly solution.

Points: 0

tree trimming and drop installation to be done or roped tree on no 105

2 Is the pole effected by the tree a Joint User Pole?(JUP)

No

Points: 0

3 Are there any special requirements or conditions that would need to be considered when carrying out tree cutting?

No

Points: 1

1 Please upload a photo of the pole.

Points: 0



2 Please upload a photo of the pole facing the house which should include the tree.

Points: 0



3 Please upload a photo from the house towards the pole. This should include the obstruction.

Points: 0



4 Please upload a photo depicting a suitable position for the bracket on the house.

Points: 0



1 Was the person who owns the tree in at the time of the survey ?

Yes

Points: 0

2 Please provide the full name of the person.

Points: 0

[Redacted]

3 Please provide a contact number.

Points: 0

[Redacted]

4 Please sign in the box below to confirm you are happy the suggested works that would be needed to achieve line of sight.

ints: 0

[Redacted]

5 Surveyor Signature Sign Off.

Points: 0

[Redacted]