

East Court, Finchampstead



A) Rotten rafter ends



B) Wood worm flight holes



C) Damaged ridge and hip rafters and distortion to purlin



D) Rotten wall plate and rafter ends at wall abutment