

Any Drainage that has been investigated should be checked against statutory records to confirm details before proceeding with any design work.

We advise that an arborologist be appointed to correctly determine the species and condition of all trees surveyed prior to any design work.

All information contained in this drawing
(including digital data) should be checked and
verified prior to any fabrication or construction.

FENCES		
BARBED WIRE FENCE	B/W	Trees
CORRUGATED IRON FENCE	CI	
CLOSE BOARD FENCE	CB	
CHESTER/T FILING FENCE	CFP	
IRON RAILING FENCE	IRI	Hedges
POST AND CHAIN FENCE	PCF	
POST AND RAIL FENCE	PRF	Walls
POST AND WIRE FENCE	PWF	
CHARLTON FENCE	CL	
LARCH LAP FENCE	LL	
INTERWOVEN FENCE	WV	Fences
WIRE MESH FENCE	WM	

ROLLBACK	RP	WATERSHED	WM
ROOF	RF	WATERFLOOD	WF
CONCRETE PAVING SLAB	CS	PAVING METHOD	PM
COVER LEVEL	CL	ROAD NAME PLATE	RNP
CURB DRIVE	CD	ROAD SIGN	RS
ELECTRIC INSPECTION COVER	EC	POSSIBLE FIRE	PF
ELECTRICITY POLE	EP	REINFORCED BRICK	RB
FIRE HYDRANT	FH	PAVEMENT TYPE	PT
FLOODING	FL	STOP SIGN	SS
FOOTPATH	FP	TELEPHONE POLE	TP
GAS VALVE	GV	TELEPHONE CABLE BOX	TCB
GRASS	GR	TRAFFIC LIGHT	TL
INSPECTION COVER	IC	UNABLE TO LIST	UTL
PUMP EXHAUST LEVEL	PE	UNCOMMON	UN
HEADLIGHT	HL	VENT PIPE	VP
MANHOLE	MM	WATER METER	WM
TRASHCLOSET	TR	EXAMINER	EX
WINDOW BELL PULL	WB	LANDSCAPE MAINTENANCE	LM
WINDOW HEAD LEVEL	WH	FLOOR LEVEL	FL
CHIMNEY LEVEL	CH	DOOR HEAD LEVEL	DH

Year	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099
1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	

North:



Indicative

Grid: Survey is based on Ordinate Survey National Grid (OSB6336) site centered on STN 2 with scale factor 1. Values have been derived via GPS using OS active network using the OSGM15 transformation and OSGM15 Geoid model.

Ordinance Datum
Drawing Title:

Topographical Drawing

Site Address:

Site Address: North of Orchard Cottage

Honey Hill, Wokingham
RG40 3BA

Client:

.....

Martin Kemball

Surveyor	MSM	Drawn By	MSM	Verified By	ATS	Date	04/04/2024
----------	-----	----------	-----	-------------	-----	------	------------

MIC No: MIC/MBS011	Rev:001
--------------------	---------

Scale:	1:200m @ A0	Date:	07.04.2024
--------	-------------	-------	------------


MIC Survey Ltd
5 Herley Wood Road Earley, Reading
Berkshire, RG6 7EE
T: 01189 668760
MILES
SURVEYS