



01 OVERVIEW FROM RADSTOCK ROAD
NTS



02 FRONT OF EARLY 17TH CENTURY COTTAGE
SOUTH WEST ELEVATION
NTS



03 SIDE NORTH-WEST
ELEVATION
NTS



04 REAR OF 20TH CENTURY EXTENSION
NTS



05 RENDERED PLINTH WITH BLACK PAINT FINISH
NTS



06 BRICK REVEALED BEHIND MISSING BOARDING
NTS



07 DECAY OF TIMBER POST (LEFT OF CH02))
NTS



08 RUST STAINING TO PAINTED FINISH ON CH02
NTS



09 CHIMNEystack CH02
NTS



10 CHIMNEystack CH01
NTS