



## KEY - TREES

	HIGH-GRADE CATEGORY 'A' TREE
	MEDIUM-GRADE CATEGORY 'B' TREE
	LOW-GRADE CATEGORY 'C' TREE
	LOW-GRADE CATEGORY 'C' TREE GROUP
	CATEGORY 'U' POOR QUALITY TREE - HAZARDOUS
	TREE TO BE REMOVED TO FACILITATE THE BUILDING WORKS
	ROOT PROTECTION AREA (RPA)
	TEMPORARY TREE PROTECTION FENCING
	CONSTRUCTION EXCLUSION ZONE - KEEP OUT!
	TEMPORARY GROUND PROTECTION TO BE REINSTATED WITH SOFT LANDSCAPING POST CONSTRUCTION
	EXISTING CHANGING ROOMS RETAINED
	NO-DIG POROUS PEDESTRIAN ACCESS PATH
	PRECAUTIONARY HAND-DIG ZONE

## BS:5837 TREE PROTECTION PLAN

CLIENT:  
MICHELLE RIDDY

SITE:  
HOLME GRANGE SCHOOL  
HEATHLANDS ROAD  
WOKINGHAM  
BERKSHIRE  
RG40 3AL


The location of the trees within the Tree Protection Plan has been taken from a topographical survey provided by the client. The position of trees should not be taken as exact but the plan is considered to be a good representation of tree locations in relation to the school site and proposed building works.

Survey by Sarah Duckworth  
Arboricultural Consultant

sarahcduckworth@hotmail.com  
M:07810440546

Scale 1:200 @ A1  
Date: MARCH 2025

Ref: HOLME GRANGE SCHOOL TPP 06663 2025 0.2



DUCKWORTHS  
ARBORICULTURE LTD.