


HSEQ Inspection (S1816291)

Today date: 25/03/2026 09:36



General Details

Date Submitted	Inspector	Job Reference	Job ID
25/03/2026 09:32	Dhrupesh Desai	S1816291	N/A
Depot Name	Inspection	Subcontractor	Points
N/A	Tree Cutting Request		1/1
Depot Manager Name	Score Percentage	Inspection Status	Contract
N/A	100%	Acceptable	
Contract Manager	Contract Number		
N/A	N/A		
Location			
Nine Mile Ride Primary School, 430 Finchampstead Rd, Berkshire, RG40 3RB			

Tree Cutting Request Inspection

100.00%	1/1	100.00%	3/3
100.00%	4/4	100.00%	2/2
Total		100.00%	

1 Please select which region you are in?
Midlands

Points: 0

1 Please give a detailed summary of the issue and possibly solution.
Tree Cutting Required To Enable Installation To Take Place.

Points: 0

2 Is the pole effected by the tree a Joint User Pole?(JUP)

No

Points: 0

3 Are there any special requirements or conditions that would need to be considered when carrying out tree cutting?

No

Points: 1

1 Please upload a photo of the pole.

Points: 0




2 Please upload a photo of the pole facing the house which should include the tree.

Points: 0




3 Please upload a photo from the house towards the pole. This should include the obstruction.

Points: 0



4 Please upload a photo depicting a suitable position for the bracket on the house.

Points: 0



1 Was the person who owns the tree in at the time of the survey ?

No

Points: 0

2 Surveyor Signature Sign Off.

Points: 0

